

Boonton PMX40 RF Power Meter Software Release Notes

2022.12.8.0 Fixed HiSLIP misidentification of queries as commands. Increased

SCPI buffer size.

Fixed issue with GPIB having inappropriate time-outs under certain

circumstances.

Fixed an issue where HiSLIP became unresponsive after numerous

connections to the instrument were opened and closed.

2020.12.17.0 Initial Release

www.boonton.com +1 973-386-9696